

Oil Field Environmental Incident Summary

Incident: 20150310120825 **Date/Time of Notice:** 03/10/2015 12:08
Responsible Party: STATOIL OIL & GAS LP
Well Operator: STATOIL OIL & GAS LP
Well Name: LUCY HANSON 15-22 6H
Field Name: CATWALK **Well File #:** 25677
Date Incident: 3/8/2015 **Time Incident:** 2300 **Facility ID Number:**
County: WILLIAMS **Twp:** 154 **Rng:** 100 **Sec:** 15 **Qtr:**
Location Description:

Submitted By: Jake Way **Received By:**
Contact Person: Jake Way
6300 BRIDGE POINT PKY, BLDG 2
SUITE 500
AUSTIN, TX 78730

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile
Distance Nearest Water Well: 1 Mile

Type of Incident Tank Leak

Release Contained in Dike Yes - Within Dike **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil	30	Barrels	30	Barrels		
------------	-----------	----------------	-----------	----------------	--	--

Brine	80	Barrels	80	Barrels		
--------------	-----------	----------------	-----------	----------------	--	--

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

None, all liquids were released into a lined (swimming pool liner) and immediately reclaimed back into the system.

Areal Extent:

Potential Environmental Impacts:

None, all liquids were released into a lined (swimming pool liner) and immediately reclaimed back into the system.

Action Taken or Planned:

All salt water tanks on location will be checked for integrity and if replaced if needed.

Wastes Disposal Location: The pea gravel inside the containment (used for traction purposes) was disposed of at PDI.

Agencies Involved:

Updates

Date: 3/11/2015

Status: Reviewed; O&G Lead

Staff: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.